KEGEL MECHANICS KLUB
Turret Multiple Indexes
Indexing trip lever not funcitoning properly
Yes
Check indexing trip lever adjustment
Or
Check for bind in linkadge between trip lever and latch
No
Time delay gear is constantly turning
Yes
Check for a broken torsion spring, or a bind in the latch. Correct as needed
No
Interlock probe is contacting torsion latch
Yes
Adjust as needed
No
Turret only indexing after the 5 pin
Yes
Commonly caused by a stretched indexing belt. Replace belt as needed
No
Turret indexing pulley loose.
Yes
Tighten pulley and check for any other loose hardware.
No
Click here to Email KMK Experts