



72/ "C" Ntfnd "C"  
switch expected but  
not found

Repair or replace

Repair or replace

Replace or adjust

Repair or replace

Table motor  
turning wrong  
direction

Bad CPU board

Blown reversing  
fuses on  
the High voltage  
board

Check fuses and  
replace if needed

Click here to email  
KMK experts

Table motor  
wired for wrong  
rotation

Move board to  
another pair of  
lanes. If problem  
moves with  
board, replace

Correct wiring

Start

No

No

No

Yes

No

No

Yes

No

No

Yes

Yes

Yes

Yes

Yes