



76/ ST Ntfnd "ST"
switch expected
but not found

Start

Clean and adjust

Spotting tong
clutch slipping

Click here to email
KMK experts

Replace or adjust

Spotting
tong switch bad
or needs
adjusted

Spotting tong
problem

Tongs damaged,
binding or out of
time

Replace solenoid

Spotting tong
solenoid bad

Bad wire
between Nexgen
box and switch

Inspect and repair or
replace