



Buffer Motor Error

Replace Fuse - 20A
P/N
154-1274

Replace Fuse Holder
P/N
153-1028

Replace Belt - Check Manual
for Proper Size

Re-Attach or Replace
P/N
158-1462

Repair Any Loose or Damaged
Wires or Replace Controller
P/N
164-8225

Click To Email KMK Experts

