



Pinsetter Cycles

Adjust as needed



Gear box clutch lever out of adjustment

Yes

No

Adjust as needed



Dashpot stop collar adjusted to high

Yes

No

Adjust as needed



180 turret interlock link adjusted to high

Yes

No

Adjust as needed

Trigger switch out of adjustment

Yes

No

Click here to Email KMK Experts

No

Time delay module sending false signals

Yes

Repair or replace as needed

No

Weak or broken spring on triggering assembly

Yes

Replace the spring

No

Bind in gear box triggering

Yes

Inspect triggering to locate bind. Inspect for loose or broken parts and replace if needed. Lubricate and adjust as needed